Example Scope of Work with Lead

225-82 - DOOR - STORM - ALUMINUM COMBINATION

Furnish and install new solid core aluminum combination storm door at the WEST--EAST---GARAGE ENTRY. Door shall be self-storing Larson #278, Cole-Sewell or equal with glass and screen inserts. Extruded door frame to be cold-rolled minimum 1" thick of rigid construction. All hardware, including hydraulic door closer and chain to be provided by manufacturer and included in this installation. Extension door sweep to be adjusted to form bottom seal and screwed securely into door. Door closer to be installed as closely as possible to center of door and installed with 3" zinc plated screws.

Materials \$	Labor \$	Total \$
271-82 -CONTAINS LE	ADWINDOWS - BASEMI	ENT - REPLACE EXISTING
Remove existing basement windows and frames. Furnish and install Andersen, Marvin or equal pre-finished thermal-pane, insulated, SLIDER vinyl units with screen. Units to match existing openings as closely as possible. Fill in and seal around frames for an air tight installation. Dispose of all debris at an approved site.		
Materials \$	Labor \$	Total \$
304-82 -CONTAINS LEADWINDOW - VINYL REPLACEMENTS Furnish and install new vinyl replacement window units in the following openings: KITCHEN-2BATHROOM-2LIVING ROOM-1 DOUBLE HUNG AND 2 LARGE DOUBLE HUNGSTAIRWAY-12ED FLOOR BATHROOM-1S/W BEDROOM-1N/W BEDROOM-1N/E BEDROOM-2. All units to be double-hung, tilt removable, with insulated, Low-E glazing and full length screens. If the trim becomes broken it shall be replaced with new to match the existing. Provide any appropriate sales brochures on the windows you are proposing to install.		
NOTE—BID TO cover ex	terior window frames with r	metal
Materials \$	Labor \$	Total \$
316-82 -CONTAINS LEAD- WINDOW - STATIONARY SASH		
Remove the existing stationary sash window located at WEST ENTRY . Furnish and install a new, VINYL stationary sash with insulated, Low E glazing. Sash shall be the same size as the original sash and shall fit snugly into the opening. Replace all damaged parting stop, blind stop, brick mold or interior trim with new to match the existing. NOTEBID TO cover exterior window frames with metal		
Materials \$	Labor \$	Total \$
318-82 -ACONTAINS LEAD WINDOW - STATIONARY SASH		
Remove the existing stationary sash window located at GARAGE WINDOWS—NSTALL A 4 PANE VINYL WINDOW. Furnish and install a new, VINYL stationary sash. Sash shall be the same size as the original sash and shall fit snugly into the opening. Replace all damaged parting stop, blind stop, brick mold or interior trim with new to match the existing. NOTE—BID TO cover exterior window frames with metal		
Materials \$	Labor \$	Total \$